#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009832 Address: 333 Burma Road **Date Inspected:** 19-Oct-2009

City: Oakland, CA 94607

**Project Name:** SAS Superstructure OSM Arrival Time: 1900 **OSM Departure Time:** 700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name: CWI Present:** Yes Wang Chuan Ging, Li Jia No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

**Bridge No:** 34-0006 **Component:** Tower/OBG

## **Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

**BAY #10** 

This QA Inspector randomly observed the following work in progress.

## **SOUTH TOWER LIFT #4**

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 052075 performing Flux Core Arc Welding process for the weld joint SSTL4-1J/L -092 located on PCMK South tower lift #4. ZPMC QC Mr. Jiang Bo monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-4333-TC-P4-F.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 050041 performing Flux Core Arc Welding process for the weld joint SSTL4-1K/L -025 located on PCMK South tower lift #4. ZPMC QC Mr. Jiang Bo monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-4333-TC-P4-F.

# WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 057266 performing Flux Core Arc Welding process for the weld joint SSTL4-1G/L -094 located on PCMK South tower lift #4. ZPMC QC Mr. Liu Zhong An monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-4333-TC-P4-F.

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 057266 performing Flux Core Arc Welding process for the weld joint SSTL4-1H/L -07 located on PCMK South tower lift #4. ZPMC QC Mr. Liu Zhong An monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-4333-TC-P4-F.

#### NORTH TOWER LIFT #3

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 040343 performing Flux Core Arc Welding process for the weld joint NSTL3-3B/K -084A located on PCMK North tower lift #3. ZPMC QC Mr. Chen Ying Xin monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-345-FCAW-2G (2F) Repair. The weld repair report identified as T-WR2016 and Ultrasonic testing (UT) report identified as T787-UT-4146.

**BAY #11** 

This QA Inspector randomly observed the following work in progress.

### EAST TOWER LIFT #4

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 040713 performing Flux Core Arc Welding process for the weld joint ESTL4-2H/L -60 located on PCMK East tower lift #4. ZPMC QC Mr. Li Tao monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-4332-TC-P5-F.

**BAY #14** 

This QA Inspector randomly observed the following work in progress.

#### **OBG SEGMENT 10AW**

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 066673 performing Flux Core Arc Welding process for the weld joint SEG059\*-007 located on PCMK splice weld between DP262A and DP235A. ZPMC QC Mr. Xu Tao monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-223(2)1T-2.

#### OBG SEGMENT 09BW

This Quality Assurance (QA) Inspector observed ZPMC qualified welder 045265 performing Submerged Arc Welding process for the weld joint SEG051\*-034 located on PCMK splice weld between DP231A and DP258A. ZPMC QC Mr. Xu Tao monitoring this welding. The welding variables recorded by QC appeared to comply with the WPS-B-T-223(2)1T-2.

# WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Unless otherwise noted, all work observed on this dated appeared to generally comply with applicable contract documents.

# **Summary of Conversations:**

No relevant conversations.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 13482570045, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Dawson,Paul	QA Reviewer